



**General Information** 





TSB #	SUBJECT	
GI-11077-016	New Charging ICON and PC Conned for R54	
MAKE[S]	MODEL[S]	YEAR[S]
N/A	N/A	N/A
S/W VERSION[S]	TOOL[S] AFFECTED	
R 54.0	400, 400+, 400SD, 500 & PRO Series	

**Overview**


The software revision 54.0 has a new look for the battery indicator as well as when connecting to the computer.

**Battery Indicator/ Charging**

This status line indicator will illustrate the remaining charge status of the battery. As different TPM types will “use up” differing amounts of energy, the indicator can only provide estimates of remaining life left before a recharge is required.

			
<b>Full Charge</b>	<b>Half Charge</b>	<b>Quarter Charge</b>	<b>Flat</b>
<b>Tool ok to use as normal</b>	<b>Ok to use – charge as soon as possible</b>		<b>Charge tool now [minimum of 5 hours]</b>

Before R54.0 battery indicator would flash while charging. (Left) Now the battery indicator will show a bolt of lightning while charging. (Right)..





## General Information

### USB Connected

Once the tool recognizes having the USB Connected then the tool will show “USB Connected”.



This message doesn't show when tool is in update mode.