



**Repair Procedure** 

**RP-61000-015**

<b>Subject:</b>	Placard Change Dodge Ram		
<b>Make(s):</b>	<b>Model(s):</b>	<b>Year(s):</b>	
Dodge (Ram)	Ram 1500, 2500, 3500	2013/14/15	
<b>Sensor(s):</b>	N/A		
<b>Tool</b>	<b>Software Version</b>		
400PRO 500	53.5		

**NOTICE: SOFTWARE BUG**

**Overview:**

Placard Value Changing with Dodge Ram as listed above does not save the new values. This bug was discovered with R53.5, but may effect earlier software.

Additionally the values are being written in the wrong order, where the tool value entered for the front axle is written to the back, and the back is to the front.

**Workaround:**

At this time there is no workaround. Software development is ongoing, and fix will be available in the next update. In the meantime, please refrain from using these Make-Model-Years for Placard Value Change until this fix is released.