Software Update

TSB #	SUBJECT	DATE
SRB-R57.0	**Tool Software Update R57.0**	**October 13, 2017**
S/W VERSION[S]	**TOOL[S] AFFECTED**	
57.0	**See Below**	

OVERVIEW

This software update increases coverage, opens additional placard adjusting coverage, and improves aftermarket sensor functionality and coverage with updating the SMP QWIK sensor program.

Feature	Exclusive	Benefit	400Plus*	400SD	500	300PRO	400PRO
Added Placard Coverage	★	2013 Dodge Ram 2500 and 3500. 2009 Dodge Ram 1500.			✔		✔
SMP QWIK Sensor Programming		Added new program from SMP for QWIK Sensor: now covers the 2 SKU program as well as the existing 3 SKU program		✔	✔	✔	✔
MY2018 Update		Update adding 176 MY 2018 Vehicles for Sensor Activations/Decode and TPMS Relearn	✔	✔	✔	✔	✔
REDI 7003A Unlock		Added the Unlock for the REDI sensor 7003A	✔	✔	✔	✔	✔
Add OBD COMMS coverage for Mercedes GLA		Added OBD COMMS for TPMS Diagnostics and Relearn for the Mercedes GLA	✔	✔	✔	✔	✔
Update Huf IntelliSens coverage.		Updated coverage for Huf IntelliSens		✔	✔	✔	✔
Updated Schrader WALII decode information		Updated to include battery information transmitted from OE sensor.	✔	✔	✔	✔	✔
Updated Mitsubishi Assisted Relearn		Improved assisted relearn process for Mitsubishi Assisted Relearn.		✔	✔	✔	✔
Updated Schrader EZ-sensor coverage		Updated coverage for Schrader EZ-sensor	✔	✔	✔	✔	✔

*Software coverage for Tech400 Plus tools with serial numbers beginning with 7.