



## Software Update

TSB #	SUBJECT	DATE
SRB-R54.1	Tool Software Update R54.1	July 15, 2016
S/W VERSION[S]	TOOL[S] AFFECTED	
54.1	See chart below	

### Overview

Software Update Release 54.1 for Bartec USA TPMS Tools. With coverage updates and other features, this update will bring your TPMS tools current. Additional features include improvements to UHF decoding along with Aftermarket Sensor Programming coverage.

Feature	Industry Exclusive	Benefit	400	400Plus	400SD	500	300PRO	400PRO
Improved UHF Decode		For Ford vehicles, the UHF decode has been improved to insure better interaction with the tool and insure proper decoding	✓	✓	✓	✓	✓	✓
Aftermarket Sensor Coverage: Huf IntelliSens		Updated coverage for Huf's IntelliSens aftermarket programmable sensors for the UVS4030/31 and 3030/31		✓	✓	✓	✓	✓
COMMS Updated		Various MMY OBD COMMS updated and corrected. More MMY coverage for TPMS Relearns		✓	✓	✓	✓	✓
Updated EZ-sensor coverage		Chrysler and Ford Coverage updated. See listing below.		✓	✓	✓	✓	✓

### Improved UHF Decode

Tools have been updated and adjusted for a more consistent interaction with Ford OE sensors.

### Aftermarket Sensor Coverage: Huf IntelliSens

This update brings the coverage for the Huf UVS3030/31 and 4030/31.





**Software Update** 

**COMMS Updated**

- 2016 Nissan Pathfinder
- 2011-15 Hyundai Veloster
- 2015-16 Nissan Versa Note



**EZ-sensor coverage updated for P/N 33500**

Make	Model	Year From	Year To
Dodge	RAM 1500	2014	2015
Dodge	RAM 2500	2014	2015
Dodge	RAM 3500 DRW	2014	2015
Jeep	Cherokee	2014	2015
Ford	Expedition	2005	2006
Ford	Freestar	2004	2005
Lincoln	Navigator	2005	2006
Mercury	Monterey	2004	2005

